

# **APPENDIX C**

## **Studies and Reports**

### **Black Creek Subwatershed Study Background Report**

#### **Prepared for:**

Region of Halton  
Town of Halton Hills  
County of Wellington  
Town of Erin

#### **Prepared by:**

Credit Valley Conservation

February 2009



FILE NAME	REPORT TITLE	FILE # or Location	SWM	EIS	Hydrog	Fish	Water Quality	Benthics	Geomorph	Erosion	Hydrology	Terrestrial	Other	Comments/Website Location
Subwatershed No. 11 - Silver and Black Creek	Silver Creek Subwatershed Study	CVC website W.2.8.01.10.			X	X	X	X	X	X	X	X		http://www.creditvalleycons.com/bulletin/resources.htm#water
Subwatershed No. 11 - Silver Creek & Black Creek	Protection and Rehabilitation for the Black/Silver Creek Subwatershed	W.2.8.01.10.			X	X	X		X	X	X	X		
Miscellaneous	Credit River Fisheries Management Plan 2002	CVC website			X								X	http://www.creditvalleycons.com/bulletin/resources.htm
Miscellaneous	misc Conservation Plans	Dave Beaton /Amy Doole			X	X	X	X	X	X	X	X		
United Aggregates Pit (Acton), Halton Hills	Section 5.0 Black Creek	R-26 HHU-92			X	X					X			
United Aggregates Pit (Acton), Halton Hills	Response to MNR: Comments With Regards To Fisheries	R-26 HHU-92			X									
United Aggregates Pit (Acton), Halton Hills	Escarpment Seep Mitigation Design & Contingency Plan Condition 24 - PTTW 02-P-3087, Acton Quarry, Acton, ON	R-26 HHU-92			X				X					
United Aggregates Pit (Acton), Halton Hills	Ecoplans - July 27, 1998	R-26 HHU-92			X						X	X		
United Aggregates Pit (Acton), Halton Hills	Water Collection & Monitoring at Acton Quarry, Annual Report 1999 (Similar reports for each consecutive year up to 2002)	R-26 HHU-92			X		X				X			
United Aggregates Pit (Acton), Halton Hills	Application for a Development Permit, Acton Quarry, Final Report - January 30, 1991	R-26 HHU-92			X		X				X			
J.C. Duff Limited, Halton Hills	J.C. Duff Sand and Gravel Ltd., Natural Environment Level 2 Assessment for the Willow Pit Amendment - November 2003	R-26 HHD-98			X	X							X	
J.C. Duff Limited, Halton Hills	Natural Environment Level 1 to Level 2 Assessment - March 2006	R-26 HHD-98			X	X							X	By: Goodban Ecological Consulting
Acton Sewage Treatment Plant	Black Creek Assimilative Capacity Study, November 2007. Part II: Assimilative Capacity Field Study Report.	W.8.03.02.HR.B.				X	X	X						By: Dillon Consulting Limited. Prepared for: Regional Municipality of Halton.
Halton Region Acton Waste Water Treatment Plant	Acton Water Quality Study Baseline Conditions	W.8.09.02.HH.A			X	X	X				X			By: Gartner Lee, January 1995
Acton Golf	CVC Issues Consolidated Report	R.12/HH/99			X	X	X	X	X	X	X	X		Golfcourse on the northside of Hwy 7 between 4th and 5th line Stantec Consulting By:
Acton Golf	Black Creek Golf course EIS	R.12/HH/99			X	X	X	X	X	X	X	X		Golfcourse on the northside of Hwy 7 between 4th and 5th line ESG By:
Acton Farm Joint Venture		R.19/HH/98			X	X	X	X	X	X	X	X		Golfcourse on the northside of Hwy 7 between 4th and 5th line
Calldron Gas Bars Ltd.		FF 08/11												Permit for Intake at the Black Creek Golfcourse (northside of Hwy 7 between 4th and 5th line); Fill File
North Halton Golf and Country Club Water Supply	North Halton Golf and Country Club - Water Taking Strategy	W.802.03.HH.B			X	X			X	X				By: Burnside, July 2000
Halton Region Prospect Park Well	Prospect Park Well Field Impact Assessment	W.8.02.02.HR.B			X		X							
Halton Region Prospect Park Well	2007 Prospect Park Wellfield Impact Assessment Final Report	W.8.02.02.HR.B			X				X					By: Dillon Consulting Limited; September 28 2007
Georgetown Water Supply Volume III	Revised Environmental Study Report, Lindsay Court Well, Georgetown, PTTW 97-P-3035	W.80101 HR-C			X	X	X				X	X		For: Regional Municipality of Halton, By: Gartner Lee, March 2004
Georgetown Water Supply Volume III	Town of Halton Hills, Lindsay Court Well Expansion, Class EA Report - November 2004	W.80101 HR-C			X	X	X				X	X		By: Region of Halton
Georgetown Water Supply Volume III	Regional Municipality of Halton, Georgetown - Cedarvale Well Field GUDI of SW Assessment 2002/2003	W.80101 HR-C			X		X				X			
Georgetown Water Supply Volume III	2006 Cedarvale well Field Impact Assessment Report - Final Draft Report	W8.01.01.HRC			X	X	X	X	X	X	X	X		By:Dillon Consulting Limited, 2006; June 12 2006
Georgetown Water Supply Volume III	Georgetown Water Supply System - 2007 Annual Report	W8.01.01.HRC			X				X					By: D.L. Bloomfield, Regional Municipality of Halton; 2007
	Halton Drinking Water Systems, Flow Summary Report				X				X	X				By: Regional Municipality of Halton; March 9 2007
	Halton Watershed Characterization Report								X					
	Halton Watershed Conceptual Water Budget Report				X				X	X				
	CVC Groundwater Model, Water Budget Update Draft Model Report				X				X					By: CVC; May 2006
	CVC Water Quality Strategy - Watershed Model Development and Application to Future Management Scenarios						X		X					By: CVC; April 2006
	Pilot Tier 3 Water Budget and Water Quantity Risk Assessment for the Town of Halton Hills (Acton and Georgetown)				X				X					
	2005 Quaternary Geology Brampton Area				X				X					Ontario Geological Survey Report 257; By: P.F.Karrow
	Nature and origin of sediments infilling poorly defined bedrock valleys adjacent to the Niagara Escarpment, southern Ontario, Canada.				X				X					By: P.A. Meyer, C.H.Eyles; 2007; Canadian Journal of Earth Sciences, 44:85-105
	Groundwater Resources Study of the Credit River Watershed, Ontario Geological Survey, Groundwater Resources Study 6				X				X					By: S.Davies, S.Holysh; 2007
	1995 Halton Aquifer Management Plan, Phase I Report, Background Hydrogeology, Regional Municipality of Halton				X				X					By: S.Holysh

